


SuperTask Lens Layout Chart



D Design Code

S1 = SuperTask 1
S2 = SuperTask 2
S3 = SuperTask 3

M Material Code

H = 1.50 Hard Resin
F = 1.60 High Index
M = 1.67 High Index
J = 1.74 Super High Index

ADD = Addition Power (two digit)